Form 731 250-10-14-08 Schober 5-2.

MICHIGAN CENTRAL RAILROAD CO.

AIR LINE DIVISION

WESTBOUNDS. TELEGRAPHIC REPORT. MOVEMENT OF TRAINS. Wednesday Dec 16th 1908 EASTBOUNDS.

Time Table No. 264 Jt 25

Westbound train 63	Westbound train 61		Station	Distance from Jackson		Eastbound train 62	Eastbound train 64
Comstock	Hickman		CONDUCTOR			Comstock	Strong
63	61		TRAIN			62	64
8983	8966		ENGINE			8988	8966
Bates	Blashfield		ENGINEER			Cudney	Blashfield
✓	✓		Air Brakes			✓	✓
			Tons				
			Time on Road				
am		M.			M.	am	am
3		Cars			Cars	3	3
1045		Depart	JACKSON JC.	1.	Arrive	None	None
		Depart	JACKSON	0.	Arrive	900	1225
1058		Arrive		5.03	Depart	846	1217
1059 R		Depart	Haires		Arrive	845 R	1216 R
"		Arrive	3-18	8.21	Depart	"	"
		Depart	Snyders		Arrive		
1120		Arrive	6-5	14.54	Depart	826	1158
1121 R		Depart	Concord		Arrive	825 R	1155 R
1135		Arrive	9	24.28	Depart	807	1140
1137 R		Depart	Homer		Arrive	805 R	1138 R
1153		Arrive	9-6	33.98	Depart	751	[illegible]
1154		Depart	Tekonsha		Arrive	750 R	1119 R
1205		Arrive	8-2	42.05	Depart	737	104
1211 R		Depart	Union City		Arrive	735 R	1258 R
"		Arrive	6-9	49-00	Depart	"	"
		Depart	Sherwood		Arrive		
1232		Arrive	5-2	54.28	Depart	715 R	1237
1234 R		Depart	Colon		Arrive	714	1235 R
1249		Arrive	6-9	61-20	Depart	703 S	1222
1250 S		Depart	Wesepi		Arrive	701	1221 R
100		Arrive	3-6 441P	64.88	Depart		
101 R	am	Depart	Centreville		Arrive		
109	3	Arrive	5-2	70-07	Depart	645 S	1206 S
113 S	605 S	Depart	Three Rivers		Arrive	3	1202 R
120		Arrive	4-7	74-78	Depart	am	1156
121 R	615 R	Depart	Fabius		Arrive		1154 R
"	"	Arrive	4-8	79.41	Depart		"
		Depart	Jones		Arrive		
142	635	Arrive	5-9	85.34	Depart		1133
143 R	636 R	Depart	Vandalia		Arrive		1128 R
154	647	Arrive	5-1	90.51	Depart		1117
156 R	648 R	Depart	Cassopolis		Arrive		1115 S
"	"	Arrive	4-3	94.73	Depart		"
		Depart	Dailey		Arrive		
212		Arrive	4-09	99.91	Depart		1056
213 R	705 R	Depart	Barron Lake		Arrive		1055 R
225	715 R	Arrive	6-5		Depart		1045
3	3	Cars	NILES	116.5	Cars		3
		Depart			Arrive		
pm	am	M.			M.		am
			Total Handled				
			Stock				
			Beef & Provision				
			Other Fast Frt.				
			Time Ordered For				

FT. WAYNE BRANCH. L. S. & M. S. RY.

FT. WAYNE BRANCH. L. S. & M. S. RY.

REMARKS AND DELAYS.

WORK TRAINS.

Conductor O. L. Smith	Eng. 8840	between Hamburg	and Aspinwall	Clear at 6 am
Conductor	Eng.	between	and	Clear at
Conductor	Eng.	between	and	Clear at
Conductor	Eng.	between	and	Clear at
Conductor	Eng.	between	and	Clear at
Conductor	Eng.	between	and	Clear at

"SYMBOLS"

A—Heavy Rain; B—Light Rain; C—Heavy Fog; D—Light Fog; F—Heavy Snow; G—Light Snow; H—Rain and Sleet; I—Heavy Wind; N—Light Wind; O—Cloudy and Threatening; R—Moderate and Cloudy; S—Pleasant; U—Very Cold; V—Very Hot; W—Storm Increasing; X—Moderating.

DESPATCHERS

Signature	D. C. Fitch	12 night M. to 730 A M. Thermo. 8 A. M.
"	E. G. Mead	730 AM. to 330 P M. " 4 P. M.
"	E. J. Whelihan	330 P M. to 1130 P M. " 12 Night
	D. C. Fitch	1130 pm to 12 night