

7/1/49

Page 92

HBS-1
(Daily)

RUN : Newberry Jct. to Suspension Bridge.

CHARACTER : Perishable, merchandise and other freight.

	<u>Arrive</u>	<u>Leave</u>	<u>Day</u>	<u>Takes</u>	<u>Drops</u>
Newberry Jct.		1:30PM	Tue.	Rdg.PN-3.	
Corning	5:30PM	6:30PM	"	HS-3	CD-2, CD-46, LS-5, P-2*.
Lyons (WD Tower)		9:30PM	"		
Rochester	11:00PM	11:30PM	"		DG-19, RS-5*, R-1*, RL-2*, RG-9*.
Depew		1:30AM	Wed.		
E. Buffalo	2:00AM	2:30AM	"		
Suspension Bridge	5:30AM		"		SD-1, MT-1*.

 * Denotes local train.

THRU SERVICE FROM POINTS BEYOND NEWBERRY JCT.

<u>Train</u>	<u>From</u>	<u>Leave</u>	<u>Arrive Newberry Jct.</u>
Rdg.PN-3	Philadelphia	11:00PM Mon.	10:35AM Tue.

THRU SERVICE TO POINTS BEYOND CORNING

<u>Train</u>	<u>For</u>	<u>Leave Corning</u>	<u>Arrive</u>
CD-2	DeWitt	7:30PM Tue.	2:00AM Wed.
CD-46	DeWitt	3:30AM Wed.	10:45AM "
LS-5	Gardenville	9:00AM "	8:30PM "

THRU SERVICE FROM POINTS BEYOND CORNING

<u>Train</u>	<u>From</u>	<u>Leave</u>	<u>Arrive Corning</u>
HS-3	Newberry Jct.	6:10PM Mon.	11:00PM Mon.

THRU SERVICE TO POINTS BEYOND ROCHESTER

<u>Train</u>	<u>For</u>	<u>Leave Rochester</u>	<u>Arrive</u>
DG-19	Gardenville	3:00AM Wed.	8:00AM Wed.

THRU SERVICE TO POINTS BEYOND SUSP. BRIDGE

<u>Train</u>	<u>For</u>	<u>Leave Susp. Bridge</u>	<u>Arrive</u>
SD-1	Detroit	12:01PM Wed.	1:40AM Thu.

 Newberry Jct. Takes Corning and beyond (except Gardenville and west).

Corning Takes Rochester Division: Rochester to Sanborn, Furniss to Model City, Attica Branch and Caledonia to Getzville.
 Syracuse Division: Coldwater to Lancaster and Churchville to Bowmansville.
 Buffalo Division: (except Gardenville and west).