

7/1/49

SH-8
(Daily)

: Suspension Bridge to Newberry Jct. (via E. Buffalo)

RUN

CHARACTER : All freight.

	<u>Arrive</u>	<u>Leave</u>	<u>Day</u>	<u>Takes</u>	<u>Drops</u>
<u>NYC</u>					
Susp. Bridge		9:00PM	Tue.	A/JS-2, JS-2.	
Niagara Falls		9:30PM	"		
Black Rock		11:00PM	"		
E. Buffalo	11:30PM	1:00AM	Wed.	SLD-6, CW-10, XN-6, NY-12, XN-2.	
By Depew		1:20AM	"		
Lyons (WD Tower)		5:00AM	"		
Geneva	5:30AM	5:45AM	"		
Corning	8:00AM	8:30AM	"		P-209*, CA-4*.
Newberry Jct.	1:00PM		"		Rdg.NP-10.

* Denotes local train.

THRU SERVICE FROM POINTS BEYOND SUSP. BRIDGE

<u>Train</u>	<u>From</u>	<u>Leave</u>	<u>Arrive Susp. Bridge</u>
A/JS-2	Blue Island	12:01PM Mon.	1:40PM Tue.
JS-2	Chicago (U.S.Yds.)	6:00PM "	4:30PM "

THRU SERVICE FROM POINTS BEYOND E. BUFFALO

<u>Train</u>	<u>From</u>	<u>Leave</u>	<u>Arrive E. Buffalo</u>
XN-6	Blue Island	10:30AM Sun.	12:01PM Tue.
SLD-6	E.St.Louis	2:30AM Mon.	12:30PM "
CW-10	Toledo	12:30AM Tue.	4:00PM "
NY-12	Cleveland	11:00AM "	6:30PM "
XN-2 **	Englewood	7:30PM Mon.	8:30PM "

** Perishable and stock not requiring feed and rest.

THRU SERVICE TO POINTS BEYOND NEWBERRY JCT.

<u>Train</u>	<u>For</u>	<u>Leave Newberry Jct.</u>	<u>Arrive</u>
Rdg.NP-10	Philadelphia	9:45PM Wed.	10:45AM Thu.

Susp. Bridge to E. Buffalo Takes Pennsylvania Division - Corning and south.

Corning Takes Newberry Jct. and connections.
Drops Corning.
Presho to Lawrenceville and Westfield for P-209. All other points south (except Newberry Jct.) for CA-4.

Newberry Jct. Drops Newberry Jct. and connections.