

PENN CENTRAL TRANSPORTATION COMPANY FREIGHT TRAIN CONDUCTOR'S DELAY REPORT

Train ML9 Engine 2630 3177 2104
 Div. GSP Direction West Engineer J White Conductor Lipton
 From 40115 To 40231 Fireman ml Brakemen Muntz
 Called for 12:35 M
 Engine left house M Engine on 5 M Train ready 5 M
 Departed initial yard M Departed Terminal 115 6-19- 19 73

CARS	LOADED		EMPTY	TOTAL
	Out of Terminal	Into Terminal		
Out of Terminal	9	56	65	
Into Terminal	-	-	-	
Handled	-	-	-	

Radio checked AS - OK
 Rear - #25 - OK 2655
 Cab 21528

TONS	
ACTUAL	ADJUSTED
2655	

TIME ON DUTY { Train Crew 12:05 M
 Engine Crew M
 Overtime Hours Minutes
 TIME OFF DUTY { Train Crew 6:00 a M
 Engine Crew M
 Overtime Hours Minutes
 Arrived 4:00 6-19- 19 73 Actual Time on Duty 5 Hours 55 Minutes

INSTRUCTIONS

Report must be made covering each trip and forwarded to Trainmaster's office immediately after arrival at terminal. In case of delays caused by car failures, give car initials and number, where taken in train and left. Where delay results from two or more causes, show actual time for each cause entering into the total delay. Show under "Delays" detention at station and reason for delay.

ARRIVE	DEPART	CARS		STATION	DELAYS
		Left	Picked Up		
105	115	9		Lithomas	Car leaving yard. set off 9 cars
310	325			Woodslie	Hat Box Detector - train OK
345				Haward Ave	arrival
400				Detrol	Tunnel - arrive

